

Under Review Notification

Raised By: M. Bellavance

Product #: 649.4701

Date: 18.02.27

Product Name: Cable Cutters Kit

| Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1) | Drawing or Document & <u>Current</u> Affected Revision for each part listed | "Y" or "N" Required for Each Part Do not leave blank | | | | | | | Reserved ECN Log Number | Instructions Relevant to Each Part (including whether CHG #'s will be affected) |
|--|---|---|--------------------------|------------------|-----------------|---------------|------------------|---|-------------------------|--|
| | | HOLD SHIPMENT | Red Tag/Quarantine Stock | Advise Customers | Stop Production | Re-Work Stock | IPF Under Review | Product Specifications Under Review ("Bluefiles") | | |
| 649.4701 | 649.4700 Rev. E2 | N | Y | Y | Y | Y | Y | Y | 18-577 | BOM Change (hardware update + new part) |
| 649.4811 | 649.4800 Rev. D1 | N | Y | N | Y | N | Y | N | 18-577 | Change shape per AWPC. |
| 649.4813 | 649.4800 Rev. D1 | N | Y | N | Y | N | Y | N | 18-577 | Change shape per AWPC. |
| 649.4816 | 649.4800 Rev. D1 | N | Y | N | Y | N | Y | N | 18-577 | Change shape per AWPC. |
| 649.4819 | 649.4800 Rev. D1 | N | Y | N | Y | N | Y | N | 18-577 | Change shape per AWPC. |
| 649.4820 | 649.4800 Rev. D1 | N | Y | N | Y | N | Y | N | 18-577 | Change shape per AWPC. |
| 649.5111/.5112 | 649.5100 Rev. C | N | Y | N | Y | N | Y | N | 18-577 | Change shape per AWPC. |
| 649.5113 | 649.5100 Rev. C | N | N | N | N | N | N | N | 18-577 | New per AWPC. |
| 649.5212/.5214 | 649.5200 Rev. B | N | Y | N | Y | N | Y | N | 18-577 | Change shape per AWPC. |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Description of Issue:

There are currently 2 issues associated with this kit:

- The current kit configuration is compatible with AW119 MKII S/N 14941 and subsequent (bolted windshield design) however it is not compatible with the earlier riveted windshield configuration (S/N 14940 and earlier). A warning was added in our system to prompt Sales to ask customers to confirm their aircraft S/N. If S/N 14940, an earlier Revision Kit will be supplied. Revision TBD within the coming days.
- AWPC requested some changes to improve installation time of 649.4701 on their assembly line.

NOTES:

1) Kits in stock are OK to sell/ship to customers/operators with AW119 MKII S/N 14941 and subsequent.

2) DO NOT SELL/SHIP CURRENT STOCK TO AWPC. ALL AWPC ORDERS TO SHIP AFTER THE RELEASE OF ECN18-577.

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider